

Rudolph Technologies AXI-940B

- *****NO HDD will come with this Tool *****
- Rudolph AXI-940B
- Tool was not in working condition when removed from the fab.
- This is the list of known Issues / Missing Parts:
 - Mapping Amplifier not operable / in Fab storage area
 - Brightfield Power Supply not operable / in fab storage area
 - Silos Inspection Board – Bad
 - Review Camera – Bad
 - Inspection Camera – Bad



Micron Tool ID	1138669	AGSS / Adelis Tool ID	RMMT20071
Manufacturer	Rudolph Technologies	Model	AXI940B
Serial Number	AXI-1253	Process	Wafer Inspection
Vintage	2010	Wafer Size	300mm
Current Status	In Warehouse	Location	Singapore